

In the Drawings:

Please add new figures 5-10, as shown on the attached sheets.



Figure 5





Figure 6 - Illustration of a Hohmann Transfer (Prior Art)



ATT BAND OF LOW



Figure 7



Figure 8




Figure 10







Figure 9 - Illustration of a Fast Transfer (Prior Art)



ewar_y and every

Walnut of the